
26 March 2019 Storm






25 March - Preparations

- Severe weather warning issued
- EOC activated on 25 March
- Liaison with external agencies
- Contractors put on standby



26 March - Storm Damage

- Approximately 400km from Kumara Junction to Jackson's Bay
- State of Emergency declared
- Surface flooding around the region
- Landslips
- Rising rivers and bridge losses
- Power / telecommunications outages
- Roads compromised





Upper Kokatahi Road – River Washout



Hari Hari Highway – Surface Flooding



Lansburgh Bridge - Washout



Fording the Waiho River after bridge washed away



Rose Creek – Debris buildup



Building Community Resilience

- Emergency Operations Centre
- Volunteers
- Communications and emergency Resources
- Iwi contribution



Civil Defence Training Session – Franz Josef



Fox Glacier Landfill



Mills Creek Slip

- Largest slip in NZ
- Moving 11 cm a day and 70 cm after heavy rain
- Slip contains 70 million cubic metres of material
- Side of the mountain is literally falling down




Fox Glacier Material

- Remote areas
- Health and Safety
- Specialist teams for the river bed







Fox Landfill Response and Recovery



- EOC on site
- Temporary protection works



Fox Landfill Recovery continued

Doc took over as lead agency

- Doc staff and volunteers
- NZ Defence Force came on board, assisted with the clean-up and provided helicopters to get to the remote sites
- Council remained involved, carting material to open landfills in the district
- Longer term solutions being identified



What now?

- In the medium term further protection works are required
- Options for long term permanent solutions being considered
 - Further Capping
 - Digging out landfill and moving material
- Test case for other at risk Landfills
 - Westland landfills
 - NZ at risk landfills



Questions



